



CFR:3.2(d)

Photographer: William Campbell **Certificate:** 93-R-0136

Date and Time: 9/26/2022 11:43 AM **Legal Name:** FOOTHILL COLLEGE

Inspection No: 2016090000816126 **Facility Name:** FOOTHILL COLLEGE

Description: Bubbled, cracked and missing flooring



CFR:3.2(d)

Photographer: William Campbell **Certificate:** 93-R-0136

Date and Time: 9/26/2022 11:43 AM **Legal Name:** FOOTHILL COLLEGE

Inspection No: 2016090000816126 **Facility Name:** FOOTHILL COLLEGE

Description: Bubbled, cracked and missing flooring