

ACILITY INSPECTION REPORT

Inspection Date: 4/16/2019

Facility Type: Animal Holding Facility

IACUC Members in Attendance: AV 027

Building & Room	Finding & Correction Plan	PI Response & Outcome	Covered Species	Deficiency	Correct By
<div><div></div><div></div></div>	<div>Initial inspection of facility for use by this PI. Request an earthquake readiness evaluation from EH&S to evaluate seismic bracing for the stacked aquariums and a review of the electrical system for this area.</div> <div>Request evaluations from EH&S to confirm personnel safety. Make any changes that are required by EH&S to enhance personnel safety.</div>	<div>From MLPS Buildings Manager on 5/21/19: I am in the final design process to upgrade the electrical.</div> <div>From EH&S on 6/3/19: The electrical receptacles on the left side where the pipe runs above will need to be relocated. [REDACTED] will place a work order to make the changes.</div> <div>From EH&S on 8/8/19: The electrical work has been completed.</div>	No	N/A	