



## Inspection Report

University Of Alabama At Birmingham  
720 Administration Bldg  
1530 3rd Avenue South  
Birmingham, AL 35294

Customer ID: 832

Certificate: 64-R-0004

Site: 001

UNIVERSITY OF BIRMINGHAM

Type: ROUTINE INSPECTION

Date: Jul-21-2015

### 3.125 (a)

#### FACILITIES, GENERAL.

\*\* On April 20, 2015 a ferret was found dead in its enclosure. It became stuck between the back wall and the removable wire floor in an apparent attempt to get out of the cage. The removable wire floor became wedged in place preventing the ferret from becoming unstuck. The facility found the back corner of the track that holds the removable floor to be slightly warped allowing the wire floor to drop out of the track when manipulated. The cage must be maintained in good repair to prevent injury. At the time of this inspection the facility has already repaired and modified all existing ferret cages to prevent a recurrence of this problem, thus correcting the noncompliance.

The exit briefing was conducted with Dr. Sutherland, Associate VP of ARP, Senior Clinical Veterinarian and Director of IACUC.

Prepared By:

ANNETTE CHAPMAN, D V M

ANNETTE CHAPMAN, D.V.M. USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER Inspector 6048

Date:

Aug-11-2015

Received By:

(b)(6), (b)(7)(c)

Date:

Aug-11-2015

Title: