



CFR : 3.1(c)(2)

Photographer: FORBES

Date and Time: 08-MAY-19

Inspection No: 2016082569478521

Description:

The surface of the resinous flooring is chipping and has pitting present to include the kennels for the dogs.

Certificate: 91-R-0051

Legal Name:

YAKIMA VALLEY

COLLEGE



CFR : 3.1(c)(2)

Photographer: FORBES

Date and Time: 08-MAY-19

Inspection No: 2016082569478521

Description:

The surface of the resinous flooring is chipping and pitted, especially in high traffic areas.

Certificate: 91-R-0051

Legal Name:

YAKIMA VALLEY

COLLEGE



CFR : 3.1(c)(2)

Photographer: FORBES

Date and Time: 08-MAY-19

Inspection No: 2016082569478521

Description:

Resinous flooring has chipped and pitted surface.

Certificate: 91-R-0051

Legal Name:

YAKIMA VALLEY

COLLEGE



CFR : 3.1(c)(2)

Photographer: FORBES

Date and Time: 08-MAY-19

Inspection No: 2016082569478521

Description:

Resinous flooring has chipped and pitted surface.

Certificate: 91-R-0051

Legal Name:

YAKIMA VALLEY

COLLEGE